Milngavie PS

Planned Works Easter / Summer 2024 Revision: A (All Items -Updated)

41 Items

Friday August 30th 2024



Title: Description: Assigned To: Location: Due Date: Status: Comments:

Floor Repair Repair section in floor with plywood patch to remove hazard. EDC PM Dept


Friday April 12th 2024 Incomplete

 Repair attempted during summer holiday period. Plywood patches noted as loose, so work instruction issued to EDC PM for joiner to reattend and fix down more secure. (2024-08-30)



Title: Description: Assigned To: Location: Due Date: Status: Comments:

Water dispenser removal Remove unsued water dispenser External Contractor Dining area Friday April 12th 2024 Complete



Title: Description: Assigned To: Location: Due Date: Status: Comments: Replacement Fire Door Replacement Fire door required withing Dining Area External Contractor Dining Area / Kitchen Friday July 26th 2024 Complete




Title:
Description:
Assigned To:
Location:
Due Date:
Status:
Comments:

Remove Kitchen Heater Remove ceiling height heater in kitchen no longer used. External Contractor Kitchen Friday April 12th 2024 Complete





Title: Description:	Exposed Plaster Ceiling - Kitchen EDC PM Joiner to attend and fix plywood to ceiling to box in exposed and cracked plasterwork.
Assigned To: Location: Due Date: Status: Comments:	EDC PM Dept Kitchen Friday April 12th 2024 Complete









Title:	Various areas - Plywood patches Required
Description:	Various areas in kitchen to be patched up with plywood patches to seal
	gaps.
Assigned To:	EDC PM Dept
Location:	Kitchen
Due Date:	Friday April 12th 2024
Status:	Complete
Comments:	





Title: Description: Assigned To: Location: Due Date: Status: Comments: Sink Unit Joiner to attend and plywood line below sink unit. EDC PM Dept. Kitchen Friday April 12th 2024 Complete



Title: Description: Assigned To: Location: Due Date: Status: Comments: Plywood lining Required Plywood lining required to cover flaking paint. EDC PM Joiner Kitchen Friday April 12th 2024 Complete





Title: Description: Assigned To: Location: Due Date: Status: Comments: Replace loose tap Replace or fix loose cold water tap. External Contractor Kitchen Friday April 12th 2024 Complete



Title: Description:	Socket replacement Electrician required to attend and replace double socket fitting and confirm electrics as safe.
Assigned To: Location: Due Date: Status: Comments:	EDC PM Dept. Dining Area Friday April 12th 2024 Complete



Title:Bulb ReplacementDescription:Room 8 high level light bulb replacement required.Assigned To:EDC PM Dept.Location:Room 8Due Date:Friday April 12th 2024Status:CompleteComments:





Title: Description: Assigned To: Location: Due Date: Status: Comments: Plywood patch - Room 8 Joiner to plywood patch hole in timber wall cladding EDC PM Dept. Room 8 Friday April 12th 2024 Complete




Title: Description: Assigned To: Location: Due Date: Status: Comments: Loose paint scrap back - Science Lab Painter from PM to scrap back loose paint in science lab. EDC PM Dept. Science Lab Friday July 26th 2024 Incomplete • Due to other commitments and a shortage of painters, the window of

 Due to other commitments and a shortage of painters, the window of opportunity to paint the ceiling was missed during the summer break. The work will be carried out once painters are freed from their current program of works to paint schools across the wider educational portfolio. (2024-08-30)



Title: Description: Assigned To: Location: Due Date: Status: Comments: Plywood patch corners - small gym hall Joiner to plywood line around all window openings in small gym. EDC PM Dept. Small Gym Hall (Upper School) Friday April 12th 2024 Complete



Title: Description:	Paint Ceiling - Small Gym Hall Painter required to stain block area showing water damage and paint white.
Assigned To: Location: Due Date: Status: Comments:	 EDC PM Dept. Small Gym Hall (Upper School) Friday July 26th 2024 Incomplete Due to other commitments and a shortage of painters, the window of opportunity to paint the ceiling was missed during the summer break. The work will be carried out once painters are freed from their current program of works to paint schools across the wider educational portfolio. (2024-08-30)





Title:	
Description:	
Assigned To:	
Location:	
Due Date:	
Status:	
Comments:	

DHT Office - Window Cill Repair Joiner to remove damaged uPVC and replace with plywood lining. EDC PM Dept. DHT Office Friday July 26th 2024 Complete









Title:	Scrap back loose paint or patch with plywood - Room 14
Description:	Painter required to scrap back loose paint and paint white if possible, if not EDC Joiner to attend and patch repair with 3mm plywood.
Assigned To:	EDC PM Dept.
Location:	Room 14
Due Date:	Friday July 26th 2024
Status:	Incomplete
Comments:	 Painter attended however the teacher was in the classroom and yellow display paper had been removed. Noted that paperwork not removed fully causing the decoration to look worse than it actually is. In addition years of staples left in walls so painter unable to paint until staples removed.

(2024-08-30)



Title: Description: Assigned To: Location: Due Date: Status: Comments: Plywood Patch ceiling - Room 12 Joiner to patch area with plywood EDC PM Joiner Room 12 Friday April 12th 2024 Incomplete

• This has been missed by the joiner, work instruction issued for them to re-attend and patch the hole with plywood. (2024-08-30)



Title:
Description:
Assigned To:
Location:
Due Date:
Status:
Comments:

Damaged window frame - Room 11 Joiner to patch around full window and collect with plywood. EDC PM Dept. Room 11 Friday April 12th 2024 Complete



Title:
Description:
Assigned To:
Location:
Due Date:
Status:
Comments:

Damaged window frame - Room 9 Joiner to line window frame with plywood. EDC PM Joiner Room 9 Friday April 12th 2024 Complete



Title:	Ceiling repairs - Room 10
Description:	Joiner to attend and cover areas of previous leaks with 3mm plywood
Assigned To:	EDC PM Dept.
Location:	Room 10
Due Date:	Friday April 12th 2024
Status:	Complete
Comments:	







Title: Description: Assigned To: Location: Due Date: Status: Comments: Room 10 - plywood patch header Joiner to renew header with plywood EDC PM Dept. Room 10

Complete



Title: Description:

Assigned To: Location: Due Date: Status: Comments: Plywood patch ceiling - Main Hall (2nd Floor) Joiner to attend and cut away damaged plasterboard and replace with suitable thickness plywood patch. EDC PM Dept. Main Hall (2nd Floor) Friday April 12th 2024 Complete



Title: Description: Assigned To: Location: Due Date: Status: Comments: Staff toilet Window Joiner to relije window Cill ann internal frame with plywood after cleaning EDC PM Dept. Staff Toilet Friday April 12th 2024 Complete





Title: Description: Assigned To: Location: Due Date: Status: Comments: Staff toilet - Box in pipework Joiner to box in pipework with plywood EDC PM Dept. Staff toilet Friday April 12th 2024 Complete



Wet wall behind sink - Staff toilet
Joiner to line back of sink and wall with white wet wall panelling.
EDC PM Dept.
Staff toilet
Friday July 26th 2024
Complete





Title:Reline and face window frame and cill with plywood.Description:Joiner to reline and face window frame and cill with plywood.Assigned To:EDC PM Dept.Location:Mrs McElmey OfficeDue Date:Friday April 12th 2024Status:CompleteComments:Image: Complete



Title: Description: Assigned To: Location: Due Date: Status: Comments: Staff toilet - false ceiling / replace light
EDC PM to fit false ceiling and new light fitting
EDC PM Dept.
Staff toilet
Friday July 26th 2024
Incomplete
Attempt made for false ceiling to be installed however the current construction of the ceiling using concrete slabs meant it was not possible, so work instruction issued for light to be replaced in the short term.

(2024-08-30)



Title: Description:	Staff toilet reline window frame Window frame to be finished in plywood lining, facing and cill once cleaned.
Assigned To:	EDC PM Dept.
Location:	Staff Toilet
Due Date:	Friday July 26th 2024
Status:	Incomplete
Comments:	 Joiner never completed due to an issue with the ceiling (see previous item on report). This will need to be looked at long with wider bathroom and addressed in due course. (2024-08-30)



Title: Description:

Assigned To: Location: Due Date: Status: Comments: Resource Room - Clean windows and then reline Cleaning company will attend and treat area, once complete joiner will attend and reline window frame and cills back to acceptable standard. EDC PM Dept. Resource Room Friday July 26th 2024 Complete



Title: Description: Assigned To: Location: Due Date: Status: Comments: Resource Room - Plywood line walls Joiner to line current timber cladding with plywood to replace walls. EDC PM Dept. Resource Room Friday July 26th 2024 Complete



Title: Description: Assigned To: Location: Due Date: Status: Comments: Girls toilet - Replace missing cover Joiner to cut plywood patch to size as replacement cover for sink unit. EDC PM Dept. Girls toilet Friday April 12th 2024 Complete









Title:	Lower School - Damaged Ceiling Replacement
Description:	Joiner to cut away damaged plasterboard and replace with plywood patch.
Assigned To:	EDC PM Dept.
Location:	Lower School Corridor
Due Date:	Friday April 12th 2024
Status:	Complete
Comments:	



Title: Description: Assigned To: Location: Due Date: Status: Comments:	Classroom 1 - Ceiling Tile Replacement Joiner to replace 20 water damaged ceiling tiles in classroom. EDC PM Dept. Classroom 1 (Lower School) Friday April 12th 2024 Complete • Works complete however new water damage since work carried out. Estates Team exploring options to in coming weeks to resolve the issue. (2024-09-02)
--	---



Title: Description:	Room 5 - Ceiling Tile Replacement Joiner to replace 20 water damaged ceiling tiles in classroom. (High Level)
Assigned To:	EDC PM Dept.
Location:	Room 5 (Lower School)
Due Date:	Friday April 12th 2024
Status:	Complete
Comments:	 Works complete however new water damage since work carried out. Estates Team exploring options to in coming weeks to resolve the issue. (2024-09-02)



Title: Description:

Room 5 - Window Clean

FM Building Manager to confirm if window can be opened for cleaning. If not able to open we will ask for a joiner to attend and open up window to allow cleaning and then close window. EDC FM Service Room 5 (Lower School) Friday April 12th 2024 Complete

Assigned To: Location: Due Date: Status: Comments:



Title: Description:	Room 3 - Ceiling Tile Replacement Joiner to attend and replace missing ceiling tiles and any water damaged tiles.
Assigned To:	EDC PM Dept.
Location:	Room 3
Due Date:	Friday April 12th 2024
Status:	Complete
Comments:	 Works complete however new water damage since work carried out. Estates Team exploring options to in coming weeks to resolve the issue. (2024-09-02)



Title: Description:	Room 2 - Ceiling Tile Replacement Joiner to attend and replace missing ceiling tiles and any water damaged tiles.
Assigned To: Location: Due Date:	COMPLETED - MAJOR NEW WATER DAMAGE SINCE WORK EDC PM Dept. Room 2
Status: Comments:	Complete



Title: Description:	Lower Gym Hall - Patch hole Joiner to patch repair hole in wall with plywood after survey carried out by another service and left with exposed wires.
Assigned To: Location: Due Date: Status: Comments:	EDC PM Dept. Lower School - Gym Hall Friday April 12th 2024 Complete



Title: Description: Assigned To: Location: Due Date: Status: Comments: Heater Repair Electrican to check heater is working and repair or replace if required. EDC PM Dept. Lower School - Staff Room Friday April 12th 2024 Complete



Title:	Main Door Lower School
Description:	BM to report on hub and glazer will attend to repair.
Assigned To:	External Contractor
Location:	Main Door Lower School
Due Date:	Friday April 12th 2024
Status:	Complete
Comments:	